

Charlotte Storm Water Services / Construction

619 Cedar St Storm Drainage Improvement Project

This project is located on South Cedar Street between Stadium View Drive and Westmere Avenue. The existing drainage system consists of a culvert under a city-maintained road. The Project consists of replacing a failing culvert crossing at 619 Cedar St. with new installation of a box culvert.

Last Updated: 05/09/23

Details

Posting Number 2025-Q1(Jan-Mar)-CSWS-17249

Anticipated Posting Date 2025-02-04

Commodity Code(s): 74505, 91200, 91244, 91345, 92912, 92915

Requirements

For Questions, Contact:

Jaime Thompson

City Contact

Jaime.Thompson@charlottenc.gov